



Metal, Rock & Glass

Instructor: Trent Leach

Required Supplies:

- Leather Welding Apron
- Cotton or Jean Pants (no shorts)
- Long Sleeve Cotton Shirt or Smock
- Leather Gauntlet Style Welding Gloves
- Steel Toed Boots
- Welding Helmet if you prefer your own
- Cotton Welding Cap for under your helmet if desired